

3875 Embassy Parkway Fairlawn, OH 44333

855.753.5474 koroseal.com



Galerie is enhanced with the colors of a painter's pallet. The troweled vertical lines of the texture pick up the colors in rich, brilliant tones. Galerie reminds us of the stolen beauty of the past colored to perfection.

		US UNITS	METRIC UNITS	
Total Weight		20.0 oz. PLY 13.3 oz. PSY	618 g PLM 451 g PSM	
Roll Width		53" – 55"	134 cm - 140 cm	
Gauge		.022"	0.559 mm	
Fabric		Woven		
Tensile (Minimum)		$50 \times 55 \text{ lb}_{\text{f}}$	222 x 245 N	
Tear (Minimum)		25 x 25 lb <sub>f</sub>	111 x 111 N	
Federal Spec.		CCC-W-408D, Type II		
WA Spec.		WA-101, Type II		
ASTM F-793		Category V, Type II		
Fire Testing		NFPA 101® Life Safety Code® NFPA 255 (ASTM E-84, CAN S102M)) Tunnel Test¹ Class A Rating Flame Spread – 10 Smoke Developed 5 NFPA 286 Corner Burn Test² Meets requirements for Flame Spread, Smoke Developed and Flashover		
CE Certification		EU classification in accordance with EN 15102:2007 + A1:2011		
Indoor Air Quality		California 01350 - Meets emission requirements for schools and offices		
Repeat	Vertical Horizontal Nominal Information Match Information	N/A N/A 51" Reverse		
1 When applied t	o GRC board with A-848-B adhesive	2 When applied to 5/8" Type-X-G	ypsum board with A-848-B adhesive	

## Available in 30 Colorways

G222-10 Earnest	G222-21 Hope	G222-99 Birnbaum
G222-09 Portrait	G222-82 Apple Tree	G222-60 Raw Umber
G222-35 Naples	G222-53 Birch Forest	G222-78 Cassone
G222-37 Expectation	G222-43 Sepia	G222-80 Woman in Gold
G222-55 Baroness	G222-45 Ochre	G222-69 Fritza
G222-70 Red Hilda	* G222-88 Tree of Life	G222-98 Smoke
* G222-71 Marie	* G222-65 Goldfish	G222-59 Byzantine
* G222-75 Portrait of a Lady	G222-42 Rosewood	* G222-58 Bronze Age
G222-91 Poplar	* G222-38 Sienna	G222-68 Nouveau
G222-56 Himalaya	* G222-57 Gold Leaf	G222-40 Still Pond

<sup>\*</sup> These decorative metallic wallcoverings should only be cleaned with mild ingredients such as soap, detergent and water. Stronger, more alkaline household cleaners have the potential to damage the surface of the material along with excessive scrubbing.